













	-10°C ... +70°C	-5°C ... +35°C			6 mm 1,5..4 mm² 1,5..2,5 mm²
	P	U, f			
	< 1 W	230 V~ 50 / 60 Hz			
			10°C ... 30°C $\Delta K = \pm 2K$	250 V~ 8 A, $\cos \varphi = 1$ 2 A, $\cos \varphi = 0,6$	









			ΔK
-10°C ... +70°C	-5°C ... +35°C	 1 ... 6 (10°C...60°C)	± 2K




			P	U
≤ 20 m	250 V~ 16 A, cos φ = 1	6 mm 1,5, 4 mm² 1,5, 2,5 mm²	< 1 W	230 V~ 50 / 60 Hz






Load






Temperature sensor



7 °C ... 50 °C





OFF 	
	
 7 °C	

